




PACKAGING INSTRUCTION:

1. STAPLES SHOULD ONLY BE USED TO SET UP CARTON  
ALL CARTONS CLOSURES MUST BE DONE WITH TAPE.
2. FILL PACKAGING REEL WITH THE QUANTITIES AS INDICATED  
IN THE CHART.



PRODUCT P/N	PARTS PER SHIPPING CARTON	PARTS PER REEL (S.P.Q.)	TOTAL REELS PER PRIMARY CARTON
W-N3-CH100-UXXA	4000 (PCS)	400 (PCS)	10

1. QUANTITY: 400 PCS

2. COVER TAPE PEELING FORCE:



3. PART DIMENSIONS MEET EIA-481-D REQUIREMENT



				一般公差 GENERAL TOLERANCE		绘图 DR.	李兴泽	料号 PART NO.	文件编号 NUMBER	 TERMINAL&CONNECTORS		
				X.X ±0.30	X* ±2'	校对 CHK.		W-N3-CH100-UXXA	ENDPT01			
				X.XX ±0.20	X.X' ±1'	审核		品名 TITLE		比例 SCALE 1/1 SHEET 1/1 版次 REV. A0		
A0	20.10.19	新图面发行	李兴泽	X.XXX ±0.10	▲ MAJOR DIM.	核准 APPD.		USB3.0 AF R/A DIP RVS TYPE CH=-1.0(包装规范)				
版次 REV.	日期 DATE	变更内容 DESCRIPTION	审核 CHK.	核准 APPD.	单位 UNIT mm							