

环保物料


PACKAGING INSTRUCTION I:

1. STAPLES SHOULD ONLY BE USED TO SET UP CARTON
ALL CARTONS CLOSURES MUST BE DONE WITH TAPE.
2. FILL PACKAGING REEL WITH THE QUANTITIES AS INDICATED
IN THE CHART.




PRODUCT P/N	PARTS PER SHIPPING CARTON	PARTS PER REEL (S.P.Q.)	TOTAL REELS PER PRIMARY CARTON
W-N3-CH184-T26	3500 (PCS)	350 (PCS)	10

1. QUANTITY: 350 PCS

2. COVER TAPE PEELING FORCE:



3. PART DIMENSIONS MEET EIA-481-D REQUIREMENT



					一般公差 GENERAL TOLERANCE		绘图 DR.	料号 PART NO.	文件编号 NUMBER	 TERMINAL&CONNECTORS			
					X.X ±0.25	X" ±2"	校对 CHK.	W-N3-CH184-T26	ENDPT01				
					X.XX ±0.20	X.X" ±1"	审核 CHK.	品名 TITLE			比例 SCALE	SHEET	版次 REV.
					X.XXX ±0.10	▲ MAJOR DIM.	核准 APPD.	USB3.0 AF R/A DIP RVS TYPE			1/1	1/1	A1
版次 REV.	日期 DATE	变更内容 DESCRIPTION	审核 CHK.	核准 APPD.	单位 UNIT	mm		CH=0.84MM(短壳)					